	Туре	L #	Hits	Search Text
1	BRS	L1	3	(pierc\$3 adj2 (roll or flare)) near3 rivet\$3
2	BRS	L2	0	(selfpierc\$3 adj2 (roll or flare)) near3 rivet\$3
3	BRS	L3	0	(self-pierc\$3 adj2 (roll or flare)) near3 rivet\$3
4	BRS	L4	15	((self-pierc\$3 adj2 rivet\$3) or (selfpierc\$3 adj2 rivet\$3)) and (\$computer or \$processor or cpu)
5	BRS	L5	185	rivet\$3 with (program\$4 or software)
6	BRS	L6	49	instruct\$4 near7 rivet\$3

	DBs	Time Stamp	Comments	Error Definitio	Errors
1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:09			0
2		2004/09/06 08:10			0
3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:11			0
4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:12			0
5	JPO; DERWENT; IBM_TDB	2004/09/06 08:12			0
6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:14			0

	Туре	L #	Hits	Search Text				
7	BRS	L7	185	rivet\$3 with (program\$4 or software)				
8	BRS	L8	16	((self adj pierc\$3 adj2 rivet\$3) or (selfpierc\$3 adj2 rivet\$3)) and (\$computer or \$processor or cpu)				
9	BRS	L9	15	((self-punch\$3 adj2 rivet\$3) or (selfpunch\$3 adj2 rivet\$3) or (self adj punching adj rivet\$3))				
10	BRS	L10	15	(rivet near7 protrud\$) with (sense\$1 or sensing or detect\$4 or measur\$3 or measurement)				
11	BRS	L11	7	(rivet near7 flush) with (sense\$1 or sensing or detect\$4 or measur\$3 or measurement)				

	DBs	Time Stamp	Comments	ErrorDefinitio	Errors
7	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:16			0
8	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06			0
9	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06			0
10	JPO; DERWENT; IBM_TDB	2004/09/06 08:21			0
11	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:22			0